## LASERFICHE FILE TRANSMITTAL FORM DIVISION OF WASTE MANAGEMENT HAZARDOUS WASTE SECTION

Daniel Girdner Your Name:

Document Category: Facility

Document Group: Inspection/Investigation (I)

Document Type: Compliance Evaluation Inspection (CEI)

EPA ID: NCD071574164

Facility Name/Subject: Former Seaboard Chemical Corporation

Document Date: 02/15/2023

(or Inspection Date)

Description:

AOC TSD Attachment list for groundwater remediation, VSQG.

No Violations.

Daniel Girdner Author:

Branch/Unit: Compliance Branch-Eastern Region

Facility/Site Address: 5899 Riverdale Drive

Facility/Site City: Jamestown


Facility/Site State: North Carolina

Facility/Site Zipcode: 27263

Facility/Site County: Guilford

File Room Use Only

	Month	Day	Year
Date Received by File Room			
Date Scanned			



## STATE OF NORTH CAROLINA DEPARTMENT OF ENVIRONMENTAL QUALITY DIVISION OF WASTE MANAGEMENT HAZARDOUS WASTE SECTION COMPLIANCE EVALUATION INSPECTION (CEI) REPORT

1. FACILITY INFORMATION:

Name: Seaboard Chemical Corporation

EPA ID Number: NCD071574164

Type of Facility: Administrative Order in lieu of a traditional Post-Closure Permit; VSQG

Facility Location: 5899 Riverdale Drive, Jamestown, NC 27263

County: Guilford

2. AUTHOR OF REPORT: Dan Girdner, Environmental Specialist II, HWS, NCDEQ

919-621-7747 <u>daniel.girdner@ncdenr.gov</u> PO Box 632, McLeansville, NC 27301

3. FACILITY CONTACTS:

Craig Coslett, Administrator, de maximus, inc., (Project Coordinator, main consultant for the PRPs)

Mailing Address: 1550 Pond Road, Suite 120, Allentown, PA 18104

Phone Number: 610-435-1151 Mobile: 610-360-7539

Email: ccoslett@demaximis.com

Amos Dawson III, Attorney, Williams Mullen (Attorney for the PRPs)

Mailing Address: 301 Fayetteville Street, Suite 1700, Raleigh, NC 27601

Phone Number: 919-981-4010

Email: adawson@williamsmullen.com

Gary Babb, P.G., Babb & Associates, P.A. (Contractor)

Mailing Address: 5506 Bradford Pear Ct, Raleigh, NC 27606

Phone Number: 919-605-4719 Email: gbabb@gmail.com

Bruce Ashley, Attorney, Fox Rothschild LLC (Attorney for the City of High Point)

Mailing Address: 230 N. Elm Street, Suite 200, Greensboro, NC 27401

Phone Number: 336-378-5321

Email: <u>bashley@foxrothschild.com</u>

J Brooks Reitzel, Jr., (Bankruptcy Attorney)

Contact Address: SunTrust Bank Building, 1301 Eastchester Drive, Suite 201,

Mailing Address: P.O. Box 5544, High Point, North Carolina 27265

Phone Number: 336-885-7900

Email: eitzel@northstate.net

**4. SURVEY PARTICIPANT(S):** Gary Babb, PG (Babb & Associates); Rich Glover, PE (Jamestown Eng. Group); Craig Coslett (de maximus, inc.); Robby Stone (City of High Point); Eric Aufderhaar, Environmental Program Consultant (NCDEQ); Josh Hanks, Hydrogeologist (NCDEQ);

**5. SURVEY INSPECTOR:** Dan Girdner, Environmental Specialist II, NCDEQ; Eric Aufderhaar, Environmental Program Consultant (NCDEQ);

- **6. DATE OF INSPECTION:** February 15, 2023 START: 1:30 PM END: 4:30 PM
- 7. PURPOSE OF EVALUATION: An annual inspection to determine compliance with the hazardous waste management requirements set forth in North Carolina Solid Waste Management Act, N.C.G.S. Chapter 130A, Article 9, and the North Carolina Hazardous Waste Management Rules, 15A NCAC Subchapter 13A.

## 8. FACILITY DESCRIPTION:

**Summary:** Seaboard Chemical Corporation is a closed Treatment, Storage and Disposal (TSD) facility that is bankrupt and undergoing closure. The Seaboard Group, Potentially Responsible Parties (PRPs) have removed all chemicals stored above ground. The Seaboard Group II was formed to address subsurface contamination and remediation. Since the subsurface contamination incorporates the City of High Point's landfill site adjacent to Seaboard Chemical's property, the City of High Point is working in conjunction with the Seaboard Group II in the remediation effort. The Hazardous Waste Section completed the five-year review of the hazardous waste land disposal permit in accordance with the requirements specified in 40 CFR 270.50 (d) as adopted in 15A NCAC 13A .0113 (h) without modification, in a letter dated January 8, 2021. The facility is also notified as a Very Small Quantity Generator (VSQG). The site consists of two properties. The former Seaboard Chemical facility property is located at 5899 Riverdale Drive, Jamestown, NC and consists of approximately 13 acres. The adjacent Riverdale Drive Landfill (a closed municipal solid waste landfill) consists of approximately 150 acres and bounds the Seaboard facility on two sides.

**Background:** The Seaboard Facility is comprised of approximately 13 acres of land, of which approximately 5-acre were developed for use as a plant and office area. The remaining area is undeveloped, wooded and bisected by a small unnamed stream. The Seaboard Facility is bordered to the north and east by the Riverdale Landfill, a closed municipal solid waste landfill.

Between 1974 and 1989 Seaboard Chemical Corporation operated solvent recovery and fuel blending processes at the facility and was granted Interim Status under the Resource Conservation and Recovery Act ("RCRA") as a treatment, storage and disposal facility in 1982. The facility was divided into 13 operating areas corresponding to the different activities conducted. These included, among other things, distillation, fractionation and condensation of organic solvent wastes. Seaboard also provided services such as thermo-setting monomer purification and recovery, chrome steel drum drying, solids pulverizing, batching and mixing. In addition, three surface impoundments were in service at the facility during the time that Seaboard was in operation. Other supporting operations included wastewater treatment, storage of incoming wastes in drums and above ground storage tanks, storage of certain recyclable materials in dedicated tanks and operation of two boilers located in a house. The property had also been used for chemical processing before Seaboard's ownership, during the period prior to 1974. Prior to that, time the property was reportedly used as a hog-slaughtering and processing facility.

The Seaboard Chemical Corporation ceased all activities in 1989, and the facility is no longer in operation. The Company ceased all activities when it was denied a special use permit by Guilford County. The corporation declared bankruptcy in 1989 and was not able to fund the cost of performing the necessary site closure. The property is owned at this time by the bankruptcy estate of Seaboard Chemical Corporation and administered by J. Brooks Reitzel, Jr. bankruptcy trustee.

Following abandonment of the facility by the owner, DENR requested parties that may have used the services of Seaboard Chemical Corporation in the past (also referred to as potentially responsible parties or "PRPs") attend a meeting held in Raleigh, NC in 1990. Following that meeting, Seaboard Group I was formed by the PRPs for the purpose of conducting a voluntary removal action for potentially hazardous materials remaining at the site and to develop some initial assessment information.

Removal activities were conducted during 1990 and 1992 to remove all remaining waste materials and certain tanks and equipment from the Seaboard Facility. In addition, an initial screening evaluation of the Site was performed, and a Remedial Investigation Work Plan was developed. Following that removal activity, Seaboard Group I was dissolved.

All structures at the Seaboard Facility have been removed. A second security fence has been constructed around the entire perimeter of the Seaboard Facility to prevent unauthorized access. Institutional controls and land use restrictions approved by DENR were implemented at the Site and necessary adjacent areas. Land use restrictions are placed on the property to restrict future uses that could present potentially unacceptable exposure risks (e.g., residential development, use of impacted ground water, etc.). The land use restrictions are in the form of perpetual declarations to be recorded with the property deed and/or through the development of zoning or permit restrictions against the potentially unacceptable activities. A deed declaration will describe the scope of the land use restrictions and will include a survey and property description to define the areas of concern. The VOC-impacted soils underlying the former operations area of the Seaboard Facility are currently covered by concrete pavement. As part of the remediation plan, the existing concrete pavement would be utilized and maintained as a cap to prevent direct exposure to impacted soils and reduce infiltration of rainfall and potential migration of soil contaminants. An engineering evaluation (based on a visual inspection) has determined the general integrity of the existing concrete pavement and verified its effectiveness for use as a remedial cap.

The Riverdale Drive Landfill was operated from the 1950's until October 1993. The Landfill was permitted by the North Carolina Department of Environment and Natural Resources Solid Waste Section in 1979. During Landfill operations, sections of the two tributary streams that cross the landfill property were piped and solid waste was used to fill the drainage valleys. The two streams are referred to as the Southern Intermittent Stream and the Norther Intermittent Stream. During filling of the Southern Intermittent Stream valley, a leachate collection system was installed adjacent to the stream channel to collect leachate migrating from the overlying solid waste. In 1989, a leachate collection system was added to control surface seeps (leachate leakage) along the slopes of the landfill. The leachate is collected in concrete storage tanks and then pumped to Lift Station 1 and subsequently treated along with the groundwater. From approximately 1966 to 1970, Landfill operations include the disposal and open burning of spent solvents in shallow pits located just north of the former Landfill scale house. Periodically, these burn pits were cleaned of residue that was accumulated in a mound to the south of the burn pits. Presently this mound consists of approximately 600 cubic yards of contaminated residue capped by a synthetic liner and is referred to as the "soil residue mound". Testing during the remedial investigation determined the material was not characteristically hazardous waste. The Landfill is now capped and maintained under an approved post closure plan.

Seaboard Group II ("Group") was formed to perform a remedial investigation and to prepare a baseline risk assessment, feasibility study and flow and solute transport model for the Site. Seaboard Group II was also to perform certain other functions necessary to develop a conceptual remedy for the Site. The Group entered into an agreement with the City of High Point to perform a remedial investigation since the close proximity of the landfill and Seaboard Chemical Corporation facility made joint investigation of the two sites advantageous for both the City and the Group. The Parties entered into an Administrative Order on Consent (AOC) with NC DENR on January 30, 1996 to perform the remedial investigation. The feasibility study was conducted under a separate AOC dated July 22, 1997.

Remedial investigations conducted at the Site have documented the presence of chlorinated and non-chlorinated volatile organic compounds (VOCs) in soils, landfill leachate, groundwater, and surface water. The remedial investigation results indicate that the VOC- affected groundwater is migrating to Randleman Lake, which bounds the Site along the northern and eastern property boundary of the Landfill. The Randleman Lake was created by the impoundment of the Deep River in 2006 by Randleman Lake Dam, which is located approximately 11.5 miles downstream of the Site.

The Seaboard Group II and the City of High Point entered into a Remedial Action Settlement Agreement (RASA) with NC DENR on December 29, 2008. The RASA provide for the design and implementation of the approved remedial action program for the site as well as completion and reporting of annual groundwater and surface water monitoring activities.

The proposed remedial design consisted of groundwater extraction and treatment in combination with institutional controls including site access control, recorded land use restrictions and restriction of water supply

well construction. The proposed remedy would prevent movement of contaminants into the Deep River and the Northern and Southern Intermittent Streams and prevent exposure to impacted soils and groundwater at the Site. Because this remedy would involve a long time frame, extraction of ground water at a rate necessary to contain contaminant migration is proposed. Groundwater and surface water sampling would monitor the effectiveness of the remedy to ensure that there is no unacceptable migration of contaminants to the Deep River or Randleman Reservoir.

It was determined that the most effective long-term method to accomplish the hydraulic containment of the plumes and treatment of the groundwater and leachate collected at the Site would be groundwater extraction in conjunction with leachate recovery and treatment in natural systems. This is primarily due to the presence of chlorinated and non-chlorinated organics, dense non-aqueous phase liquid organics (DNAPL), and 1,4-dioxacyclohexane (1,4-dioxane) in the shallow and deep groundwater and landfill leachate.

The Remedial Treatment System refers to the overall treatment process, which include the Physical and Natural Treatment Systems. The Main Treatment Area, or Mechanical Treatment Area (Physical Treatment) is located near the end of Recovery Way, just east of the junction with the MRF access road and the east side of the Soil Residue Mound. This is the area with the majority of the Remedial Treatment System equipment is installed in what is referred to as Enclosures 1 through 7. These enclosures house the Settling Vat, Effluent Filters, the water chemistry laboratory, the Effluent Storage Tanks, and LS-2 (the AOP Unit was removed in 2019). The Filter Building, Maintenance Building, main electrical transformer, weather station and storage enclosure are also located here. A clarifier and sludge management unit were constructed to reduce the amount of solids in the leachate prior to treatment. Currently, prior to being pumped to the cap of the landfill for phytoremediation, the leachate and groundwater from the extraction wells goes through the clarifier (for solids to settle), treatment to remove metals, and an air stripper which reduces the volatile organics concentration.

The Natural Treatment System (referred to as the Phytoremediation System) is currently established and maturing on the cap of the Landfill -- roughly 12.5 on the East Lobe and 20.5 on the West Lobe. The 33-acre tree stand consists of a variety of conifer tree species (primarily pine tree species). They are used for phytoremediation and biodegradation of the treated Remedial Treatment System process effluent. The non-native tree zones are planted with several species of conifer trees that comprise the Natural Treatment System. A buried drip-irrigation system was used for irrigation and fertigation, but has begun being replaced for line on the ground surface to facilitate monitoring and repair. A rotation of the sixteen zones occurs based on soil moisture (detected by probes).

The Declaration of Perpetual Land Use Restrictions (DPLUR) Certification was submitted on February 3, 2022.

On February 15, 2023, along with the annual inspection of the facility as a permitted TSDF, a site visit for the five-year review of the groundwater remediation system was also conducted, as required by the 2008 Remedial Action Settlement Agreement (RASA). The five-year review of the Administrative Order of Consent in Lieu of a post-closure permit was last completed by the Facilities Management Branch (FMB) in January 2021 with no modifications required at that time. The five-year review for the RASA was a remediation system performance review, and the final technical report will be submitted to DEQ for review later in February 2023.

- **9. HAZARDOUS WASTE (HW) GENERATED:** The site notified as a Very Small Quantity Generator (VSQG) on February 28, 2020, to facilitate the use of Episodic Generator events if needed for a clean-out or to discard chemicals used in the treatment system. No hazardous waste was being generated or accumulated at the site during the inspection.
- **10. AREAS OF REVIEW AND INSPECTION:** A site meeting began at the Treatment Building and LS-2 process building, where the survey and inspection participants met. Mr. Rich Glover, of Jamestown Engineering, provided a tour of the LS-2 groundwater treatment process building. The facility maintained emergency contact information and a contingency plan in binders. The treatment system was operating during the visit. The total

number of shutdowns over one day have been minimized and therefore the total gallons treated has remained relatively consistent but with an increase from approved system improvements. The information for the last calendar year will be presented in the Seaboard II group's Five-Year Review Report from February 2023.

The soil cap over the contaminated soil residue area, or Soil Residue Mound from the closed Riverdale Landfill, was intact and the grass was seasonally dormant, but provided a well vegetated cover with no visible areas of erosion, so that the synthetic cap was not exposed. The following Monitoring Wells in this area were also inspected and found to be locked, labeled, and in good condition: MW-17, MW-15A, and MW-15B.

Mr. Glover and Mr. Craig Coslett led the group to the West Phytoremediation Zone. The phytoremediation system was visually observed, with the rows of trees that appeared green and healthy. Treated water distribution line flow meters were checked, which indicated the water lines operating. Newer drip lines were observed on the surface at the base of the trees. Mr. Glover explained this was to better facilitate monitoring and repair of the irrigation lines, and that freezing was not a major concern based on the constant flow of water, and flexible lines here, but heat trace tape was used on valves and other components prior to the The increased quarterly surface water monitoring from the approved system improvements will help the Seaboard II group evaluate conditions after the irrigation line replacements. Two observation wells in the area were checked, OW-SIS-3, which was no longer in use but appeared to be intact, and OW-SF-1, which was also intact and maintained. The facility maintains lysimeters in order to compare water volume and concentration with mass removal. The facility tracks and documents phytoremediation system maintenance and performance.



Photo: 1 of 2, February 15, 2023, Western Phytoremediation Zone, (Zones 1-11), with the replacement irrigation line visible.

The group continued to the LS-1 pump-and-treat system building in the eastern area to review the leachate extraction well system and recent system improvement modifications to capture more shallow groundwater. The new wells and pumps were reportedly increasing performance in reducing constituents of concern (COC) in surface water based on sampling results, which will be demonstrated in the Five-year Report for the RASA. Spot inspection was made of wells, including the following compliance monitoring wells, observation wells, and extraction wells: MW-1, MW-3A, MW-3B, MW-3C, MW-11, PW-5D, PW-13I, PW-DR1, PW-SF1, PW-SIS1, PW-SIS4. The wells observed were well maintained, secured, identified, and labeled with drillers tags. The required groundwater and surface water monitoring activities were reportedly conducted during October 2022, with results to be submitted in the annual groundwater monitoring report and further reviewed in the Five Year Report under the RASA. The group continued around the eastern side of the landfill by vehicle. The monitoring wells were observed to be closed, secured, labeled, and maintained in good condition. The Eastern Phytoremediation Zone also appeared to be healthy.

The former Seaboard Chemical Corporation property was secured with fencing, gate, and lock. The RCRA cap over was found in good, well-maintained condition.



Photo: 2 of 2, February 15, 2023, RCRA cap facing southeast.

**SITE DEFICIENCIES:** None Observed.

## **COMMENTS AND RECOMMENDATIONS:**

- Please continue the EPA ID NCD071574164 and Seaboard name on groundwater monitoring and remediation system performance reports to facilitate report searches for electronic copies.
- The assistance of the facility contacts was greatly appreciated during the site visit. If you have any questions about this report or maintaining compliance with the (RCRA) hazardous waste management regulations, please contact me at <a href="maintaining-deq.nc.gov">Daniel.girdner@deq.nc.gov</a> or by telephone at 919-621-7747.

rev 5/30/23

Daniel Girdner
INSPECTOR (DATE)

cc: Gary Babb – <u>gbab@gmail.com</u> Eric Aufderhaar – Project Manager - <u>eric.aufderhaar@deq.nc.gov</u> Central Office Files